TOP SECRET

CONTROL NO. ____

BYE-2810-65, Copy 2

REFERRED TO	RECEIVED		RELEA	ASED	SEEN BY	
OFFICE	SIGNATURE	DATE TIM	DATE	TIME	NAME & OFFICE SYMBOL D	AT
DCI .	m. J.	8/20/6/			11	1
: 						
·						

Handle Via Indicated Controls

BYEMAN

Access to this document will be restricted to those persons cleared for the specific projects;

OXCART	••••••	/	****************
••••••			••••••

WARNING

This document contains information affecting the national security of the United States within the meaning of the espionage laws U. S. Code Title 18, Sections 793 and 794. The law prohibits its transmission or the revelation of its contents in any manner to an unauthorized person, as well as its use in any manner prejudicial to the safety or interest of the United States or for the benefit of any foreign government to the detriment of the United States. It is to be seen only by personnel especially indoctrinated and authorized to receive information in the designated control channels. Its security must be maintained in accordance with egulations pertaining to BYEMAN Control System.

TOP SECRET

GROUP 1 Excluded from automatic dawngrading and declassificatio



CENTRAL INTELLIGENCE AGENCY

2 0 AUG 1965

WASHINGTON 25, D. C.

OFFICE OF THE DIRECTOR

BYE-2810-65 Copy 2

MEMORANDUM FOR THE PRESIDENT

On 14 August 1965, an A-12 aircraft flew nonstop from its secre
base to Orlando, Florida, back to the
then to Kansas City and return to its base. The flight was
accomplished exactly as planned, simulating an operational mission
with two air refuelings and three cruise legs. On each leg of the
mission the aircraft cruised at its designed operational speed of
Mach 3.1 at altitudes between 80,000 and 90,000 feet. The flight
covered a total distance of 6500 nautical miles in 5 hours and 27
minutes, including air refueling times. A total time of 2 hours and
20 minutes was flown at cruise speed of Mach 3.1. The aircraft
landed in excellent condition with only three minor malfunctions.

The significant aspects of this flight are:

- 1. There were no air-flow disturbance conditions encountered in the engine air inlets--not even minor roughness. (This is the classic problem that plagues supersonic speed turbojet aircraft).
 - 2. There were no electrical system problems.
- 3. There were no heat problems to the aircraft engines, or pilot due to the prolonged high speed, high temperature flight.
- 4. This flight is an important milestone and increases our confidence that we should have a reliable, operational aircraft in near future. (3 to 6 months for further validation.)

(signed) W. F. Raborn

W. F. RABORN

HANDLE VIA BYEMAN CONTROL SYSTEM

GROUP 1 Excluded from automatic dewngrading and declassification

APPROVED FOR RELEASE DATE: AUG 2007

BYE-2810-65 Page 2

Signature Recommended.
Director of Office of Special Activities
Signature Recommended:
Deputy Director for Science and Technology

HANDLE VIA BYEMAN CONTROL SYSTEM

TOP SECRET

BYE-2810-65 Page 3

Distribution:

Copy 1 - Addressee

Copy 2 - DCI

Copy 3 - DDCI

Copy 4 - Ex. Dir. - Compt.

Copy 5 - ER

Copy 6 - DD/S&T

Copy 7 - DD/S&T

Copy 8 - DD/S&T

Copy 9 - D/OSA

Copy 10 - D/TECH

Copy 11 - PS/OSA

Copy 12 - SS/OSA

Copy 13 - D/FA/OSA

Copy 14 - OXC/OSA

Copy 15 - SAL/OSA

Copy 16 - RB/OSA

D/OSA/JCLedford/mcm(19 Aug 65)

HANDLE VIA BYEMAN CONTROL SYSTEM

TOP CECTE